

FIGURE 20
LABORATORY ANALYTICAL RESULTS: 5-DAY BOD and TOC
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT

Rico-Argentine Mine Site
Dolores County, Colorado




FIGURE 21
LABORATORY ANALYTICAL RESULTS: SULFATE and SULFIDE
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT

Rico-Argentine Mine Site
Dolores County, Colorado




FIGURE 22
LABORATORY ANALYTICAL RESULTS: ARSENIC
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT
 Rico-Argentine Mine Site
 Dolores County, Colorado




FIGURE 23
LABORATORY ANALYTICAL RESULTS: IRON
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT

Rico-Argentine Mine Site
Dolores County, Colorado




FIGURE 24
LABORATORY ANALYTICAL RESULTS: MANGANESE
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT

Rico-Argentine Mine Site
Dolores County, Colorado




FIGURE 25
LABORATORY ANALYTICAL RESULTS: CADMIUM
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT
 Rico-Argentine Mine Site
 Dolores County, Colorado




FIGURE 26
LABORATORY ANALYTICAL RESULTS: ZINC
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT

Rico-Argentine Mine Site
Dolores County, Colorado

